

<b>Job Id</b>	TEP	<b>Job Details</b>	Test Tower
<b>Device Serial No.</b>	31861	<b>Data log Type</b>	Multi Anchor
<b>Threshold</b>	110 %	<b>Latitude</b>	35.7421225199238
<b>Longitude</b>	-78.6315098400372	<b>Temperature</b>	36.12°F
<b>Wind Speed</b>	10.2899056 mph	<b>Wind Direction</b>	South West
<b>Date</b>	Jan-30-2019	<b>Time</b>	12:04:08

Rope Name	Rope Color	Rope Diameter	Strand	Material	Leg	Wire	Before Tension	Before Unit	Before IsOverLoad	Before Elevation	After Tension	After Unit	After IsOverLoad	After Elevation	Date	Time
1/2" 1x7 EHS (BLUE)	Blue	1/2" / 12.7mm	1x7	Galvanised	Leg A	Wire 1	25	lbs	No						Jan-30-2019	12:04:21
5/8" 1x7 EHS (BLACK)	Black	5/8" / 15.9mm	1x7	Galvanised	Leg A	Wire 2	30	lbs	No						Jan-30-2019	12:04:42
1/2" 1x7 EHS (BLUE)	Blue	1/2" / 12.7mm	1x7	Galvanised	Leg B	Wire 1	55	lbs	No						Jan-30-2019	12:05:45
5/8" 1x7 EHS (BLACK)	Black	5/8" / 15.9mm	1x7	Galvanised	Leg B	Wire 2	50	lbs	No						Jan-30-2019	12:06:10